

Howie C. Morales
Lt. Governor

NEW MEXICO ENVIRONMENT DEPARTMENT

Harold Runnels Building
1190 Saint Francis Drive, PO Box 5469
Santa Fe, NM 87502-5469
Telephone (505) 827-2855
www.env.nm.gov



James C. Kenney
Cabinet Secretary

Jennifer J. Pruett
Deputy Secretary

Certified Mail - Return Receipt Requested

September 4, 2019

Mrs. Dorothy Knezevich, Owner Howard's Sand & Gravel P.O. Box 1456 Las Vegas, New Mexico 87701

RE: Howard's Sand & Gravel; Minor; Individual Permit; SIC 1442; NPDES Compliance Evaluation Inspection; NPDES # NMU001191; August 7,2019

Dear Mrs. Knezewich:

Enclosed please find a copy of the report and check list for the referenced inspection that the New Mexico Environment Department (NMED) conducted at your facility on behalf of the U.S. Environmental Protection Agency (USEPA). This inspection report will be sent to the USEPA in Dallas for their review. These inspections are used by USEPA to determine compliance with the National Pollutant Discharge Elimination System (NPDES) permitting program in accordance with requirements of the Federal Clean Water Act.

You are encouraged to review the inspection report, required to correct any problems noted during the inspection, and to modify your operational and/or administrative procedures, as appropriate. Further, you are encouraged to notify in writing both the USEPA and NMED regarding modifications and compliance schedules at the addresses below:

David Long
US Environmental Protection Agency, Suite 1200
Enforcement Branch (6EN-WS)
1445 Ross Avenue
Dallas, Texas 75202-2733

Sarah Holcomb, Program Manager New Mexico Environment Department Surface Water Quality Bureau Source Regulation Section P.O. Box 5469 Santa Fe, New Mexico 87502 Howard's Sand & Gravel September 4, 2019

If you have any questions about this inspection report, please contact Daniel Valenta at (505) 827- 2575 or at Daniel.Valenta@state.nm.us.

Sincerely,

/s/Sarah Holcomb

Sarah Holcomb Surface Water Quality Bureau

Cc. Carol Peters-Wagnon, USEPA (6EN-WM) by e-mail David Long, USEPA (6EN-WM) by e-mail Amy Andrews, USEPA (6EN-WM) by e-mail David Esparza, USEPA (6EN-WM) by e-mail Darlene Whitten-Hill, USEPA (6EN-WC) by e-mail Robert Italiano, NMED District II by e-mail Nancy Williams, USEPA (6EN-WC) by e-mail



Form Approved OMB No. 2040-0003 Approval Expires 7-31-85

•	YEFA														
			NDDE	S Compliance	Incn	vooti	n Dono	n t							
				Section A: Natio											
	Transaction Code		NPDES	Section A. Natio	niai Da	ata Sy		yr/mo/o	lav		In	spec. Type	Inspect	or	Fac Type
1	N 2 5 3 N M U	, (0 0 1 1	9 1 11	12	1	9 0	8	0	7 1		$\begin{bmatrix} \mathbf{c} \end{bmatrix}$	19 S	20	2
					Remar	ks								-	
	S A N D &		G R A V	E L	F	A	C I	L	I	TY					
	Inspection Work Days		Facility Evaluation Ra	ting	BI		QA I I		 I	 I	 I	-Reserved	 I I		 I
	67 69		70 1	71	N	72	N 73			74 75	·				80
				Section 1	B: Fac	cility l	Data								
	ne and Location of Facility Inspected (For in	dustrial users discharg	ging to POTW, als	so incli	ıde	Entry Ti					1	Effective Dat	e	
	W name and NPDES permit number) ward's Sand & Gravel						1108/A	ugust	7, 2019	,		No Peri	mit		
Fro	m Las Vegas, NM, travel south on	I -25	approximately 8 mil	les. Exit County 1	Road I	B47	Exit Tin						Expiration Da	ate	
	d & Gravel operation on south side on ne(s) of On-Site Representative(s)/Title						1224/A	ugust	7, 2019	,	Ot	No Peri her Facility			
	Jacob Knezevich/ Site Foreman	(3)/11	ione and I ax I variable (•			
Nar	ne, Address of Responsible Official/Ti	tle/Ph	one and Fax Number					_				AT 35° 27'			
Mrs	s. Dorothy Knezevich, South Grand xico/Owner/505-425-8818 fax 505-4	d Ave	enue, P.O. Box 1456,	Las Vegas, Nev	w		Yes	X Cor	ntacted No		L	ONG 105°	16' 30.54"	W	
Mes	xico/Owner/505-425-8818 1ax 505-4	120-8	706				ies	Α	NO [SI	C 1442			
				ction C: Areas Ev											
			·	ry, M = Marginal,							1	Γ			
U N	Permit	N	Flow Measurement		N	^	erations &				N	CSO/SSC			
	Records/Reports	N N	Self-Monitoring Pro Compliance Schedu	_	N N		idge Hand etreatment	_	sposai		N	Multimed	Prevention		
N N	Facility Site Review Effluent/Receiving Waters	N	Laboratory	nes	N		orm Water				N	Other:	па		
	Emachqueerving waters		Section D: Summary	of Findings/Con					eets if	necessarv		<u> </u>			
			<u> </u>								,				
	Facility does not have permit cov	erage	e for discharges to T	ecolote Creek.											
2.	See Further Explanations.														
Nan	ne(s) and Signature(s) of Inspector	(s)		Agency/Office/	Teleph	one/I	ax					Date			
DANIEL VALENTA /s/Daniel Valenta NMED/SWQB 505-827-2575				575				9/4/2019)						
												 			
Sign	nature of Management QA Reviewer			Agency/Office/ NMED/SWQB				ers				Date	9/4/201	Q	
JEN	NIFER FOOTE /s/Jennife	r Fo	ote	THE PION QD	202-01	-, 00.	. •						7/4/401	,	

Compliance Evaluation Inspection Howard's Sand & Gravel Facility NPDES Permit No. NMU001191 August 7, 2019

Introduction

On August 7, 2019 a Compliance Evaluation Inspection was conducted at the Howard Sand & Gravel Facility (Standard Industrial Classification 1442) located at Tecolote, New Mexico by Daniel Valenta from the Surface Water Quality Bureau accompanied Amy Andrews of the U.S. Environmental Protection Agency. The purpose of this inspection was to document the facility's status regarding the process wastewater discharge into Tecolote Creek. Finding of the inspection are detailed on the attached EPA form 3560-3 and in the narrative Further Explanations section of the report.

At the Tecolote Creek site, approximately 9.6 acres, the facility processes and stores construction sand and gravel. The facility operates when needed washing/screening to process sand and gravel. The site is located next to Tecolote creek, a perennial stream. Water utilized in this process is drawn from the adjacent Tecolote Creek and then discharged into a sediment pond.

This report is based on on-site observation by NMED personnel and verbal information provided by the facility's representative Mr. Jacob Knezevich and Mrs. Dorothy Knezevich. Arriving at the site at approximately 1108. The inspector made introductions and discussed the purpose of the inspection. Working at the site was Mr. Jacob Knezevich, Site Foreman.

A brief exit interview to discuss the findings of this inspection was conducted at approximately 1224 hours with Mrs. Knezevich at her private residence. The facility's representative was briefly informed of the requirements under the NPDES program regarding permitting requirements and the need for an individual discharge permit to cover the process water being discharged from the separation/wash area of the facility.

Clean Water Act (CWA) and Industrial Stormwater Permit Requirements

Section 301 (a) of the Federal Water Pollution Control Act states that "Except as in compliance with this section and sections 302, 306, 307, 318, 402 and 404 of this Act, the discharge of any pollutant by any person shall be unlawful." Federal regulations in 40 CFR Part 122.21(a) Duty to apply (1) states: "Any person who discharges or proposes to discharge pollutants...must submit a complete application to the Director in accordance with this section and part 124 of this chapter."

The Clean Water Act prohibits discharges of "pollutants" through a "point source" into a "water of the United States" unless it is in accordance with the National Pollutant Discharge Elimination System (NPDES) permit. The permit will contain discharge limits, monitoring and reporting requirements, and other provisions to ensure that the discharge protects human health and the environment. The permit translates general requirements of the Clean Water Act into specific provisions tailored to the operations of each facility. It means any discernible, confined and discrete conveyance, such as a pipe, ditch, channel, tunnel, conduit, discrete fissure, or container.

Compliance Evaluation Inspection Howard's Sand & Gravel Facility NPDES Permit No. NMU001191 August 7, 2019

The term pollutant includes any type of industrial, municipal, and agricultural waste discharged into water. Some examples are dredged soil, solid waste, incinerator residue, sewage, garbage, sewage sludge, munitions, chemical wastes, biological materials, radioactive materials, heat, wrecked or discarded equipment, rock, sand, and industrial, municipal, and agricultural waste.

Findings

The facility does not have NPDES permit coverage for the discharge of process water from the screening and washing area. The containment pond was filled up and was overflowing bypassing the berm. The facility needs to clean and maintain the settling pond from discharging process water or apply for a NPDES discharge permit. More information and how to apply for a NPDES permit can be found at https://www.epa.gov/npdes.

NMED/SWQB


Site Overview

City/County: Tecolote, NM/San Miguel County

Location: Howard's Sand & Gravel Operation, East of Tecolote, NM on the Tecolote Creek

Subject: South side of facility boarders Tecolote Creek where screening/washing mechanism operates.

Howard's Sand & Gravel



Screening/Washing Mechanism

NMED/SWQB Official Photograph Log

Photo #1

Photographer: Daniel Valenta	Date: 8/7/2019	Time: 1110				
City/County: East of Tecolote, NM						

Location: Facing north, Howard's Sand & Gravel Facility off County Road B47 near Tecolote, NM.

Subject: Unpermitted discharge of process water from separation/washing equipment into Tecolote creek.



NMED/SWQB Official Photograph Log

Photo # 2

Photographer: Daniel Valenta	Date: 8/7/2019	Time: 1143			
City/County: East of Tecolote, NM, Tecolote Creek/San Miguel County					
Location: Facing north, Howard's Sand & Gravel Facility off County Road B47 near Tecolote, NM.					
Subject: The sediment ponds are next to Tecolote Creek. The ponds have not been cleaned and					

Subject: The sediment ponds are next to Tecolote Creek. The ponds have not been cleaned and are overflowing into Tecolote Creek.



NMED/SWQB Official Photograph Log

Photo #3

Dhotographer, Daniel Valenta	Date: 9/7/2010	Time: 1142		
Photographer: Daniel Valenta	Date: 8/7/2019	Time: 1143		
City/County: East of Tecolote, NM, Tecolote Creek/San Miguel County				
Location: Facing north, Howard's Sand & Gravel Facility off County Road B47 near Tecolote, NM.				
Subject Sand/Gravel washing area. Water is pumped from Tecolote Creek to clean the gravel ar				

Subject Sand/Gravel washing area. Water is pumped from Tecolote Creek to clean the gravel and should be retained from reentering the creek.



Submitted Site Pictures

September 18, 2019

By Mr. Eric Knezevich





